



F10, Forgeside House, Cardiff Bay Business Centre, Lewis Road, Cardiff, CF24 5FA

Statement of Cleanliness Completion Certificate

Client: RHA

Site address: 29 C105 Ynysygrug, Treataw Road, Tonypandy, CF40 2NW


Location on Site: living room

Project No: 2220AS553R Date project commenced: 16/2/2022 Date project completed: 16/2/22

Client contact name: Mr Marshman Client contact phone No: 07783452940 Mobile:

Preliminary inspection for client:	Date: 15/2/2022	Preliminary inspection for company:	Date: 15/2/22
Name: Mr Marshman		Name: J. Davies	
Signature: See Marshman		Signature: [Signature]	

Site plan:



Description of work carried out: cracks in ~~ceiling~~ ceiling, alot of tar from smoke. cleaned off, then cracks sealed with caulking to make safe. upon inspection, customer/tenant found work done to a satisfactory standard.

Completion acceptance for client:	Date: 16/2/2022	Completion acceptance for company:	Date: 16/2/22
Name: Mr Marshman		Name: J. Davies	
Signature: See Marshman		Signature: [Signature]	