



F10, Forgeside House, Cardiff Bay Business Centre, Lewis Road, Cardiff, CF24 5FA.

Statement of cleanliness Completion certificate

Client:	RHA				
Site address:	34 Graig Wen, Maerdy, Ferndale, RCT, CF43 4TW				
Location on Site:	Outside Front Porch				
Project No:	2220A5711R	Date project commenced:	18-5-22	Date project completed:	18-5-22
Client contact name:		Client contact phone No:	t: m:	e-mail:	
Preliminary inspection for client:	Date:		Preliminary inspection for company:	Date:	18-5-22
	Name:			Name:	Jane Davies
	Signature:			Signature:	
<p><u>Site plan:</u></p>					
<p>All work carried out in accordance with the HSE Approved code of practice (ACOP) L143 "Work with Materials Containing Asbestos" in conjunction with "The Control of Asbestos Regulations 2012."</p> <p style="text-align: center;"><u>Description of work carried out:</u></p> <p>Repair carried out to external front porch to undercloak. Encapsulated with PUA to prevent any loose fibres being released. Gaps then filled with caulking to further encapsulation.</p>					
Completion acceptance for client:	Date:		Completion acceptance for company:	Date:	18-5-22
	Name:			Name:	Jane Davies
	Signature:			Signature:	