

8 Abertonllwyd House, Abertonllwyd Street, Treherbert, Treorchy.					Survey Type >			Management		Initial Survey Date(s) >							05/09/2012						
2220AS729																							
Report Section	Extrapolated from Site Ref	UPRN (if applicable)	Lab Ref	Site Ref	Area or room	Position	Component description	Material	Asbestos ID	Extent / approx quantity	** A accessibility	** Damage	** Surface treatment	Asbestos type (1 = Chrysotile, 2 = Amosite, 3 = Crocidolite)	Risk ratings			Management Action					
															Total Material Risk rating "A"	Total Priority Risk rating "B"	Total Risk Rating "A+B"	PHH ENVIRONMENTAL		Last date ACM inspected	Last date ACM modified	Note	Licensed work?
																Recommendation							
G			NGAR0 0314-1	2220AS72 9-001	Kitchen	Under side sink top	Bitumen pad	Bitumen coatings on metal	Negative asbestos sample	1No	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/09/12				
H				2220AS72 9-003	Kitchen	Floor	Black vinyl	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	6SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/09/12				
H				2220AS72 9-004	Bathroom	Floor	Black/white check vinyl	PVC vinyl floor tiles & unbacked PVC flooring	Discounted material (not sampled)	4SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/09/12				
H				2220AS72 9-005	Roof space	Under roof covering	Sarking felt	Bitumen roofing felts	Discounted material (not sampled)	50SM	NA	NA	NA	NA	NA	NA	NA	No action not an ACM	05/09/12				
I			NGAR0 0314-2	2220AS72 9-002	All areas	Ceilings	'Artex' - 'Stipple'	Textured coatings & joint compound	Removed	48SM	NA	NA	NA	NA	NA	NA	NA	Record, manage & monitor	16/12/21			The sureveyor went to the property on the	