

Ground floor – Hall 1, hall 2,
kitchen and cupboard -
2220AS1189 - 004

2220AS1189 – 002
2220AS1189 - 012


2220AS1189 - 006

2220AS1189 – 001
2220AS1189 - 011

2220AS1189 - 005

2220AS1189 - 006

2220AS1189 – 002
2220AS1189 - 012




2220AS1189 – 001
2220AS1189 - 011

2220AS1189 - 007

2220AS1189 - 003

2220AS1189 - 009



Roof space
2220AS1189 - 010

Site reference points colour coding:

RED for 'positive', 'strongly presumed',
'presumed' and 'contaminated' ACMs

BLUE for 'Presumed to contain ACMs due to no
access'

GREEN for 'discounted materials', 'no asbestos
suspected' and 'negative

BLACK for 'removed' ACMs

Do not scale, not dimensionally accurate

Note:

This must be reproduced in colour and is to be read in conjunction
with the full report.



Annex III Project Ref. 2220AS1189
11 Llewellyn Street, Treherbert, Treorchy
Ground and First Floor Plan